# Approved For Release 2001/08/26 : CIA-RDP33-02415A000600050030-6 \*USAF Declass/Release Instructions On File\*

#### FOR OFFICIAL USE ONLY

DEPARTMENT OF THE AIR FORCE
1130TH AEROSPACE TECHNICAL DEVELOPMENT
AND TRAINING GROUP
Edwards Air Force Base, California 93523

ATTG Reg 66-1

2 October 1969

Depot Field and Organizational Maintenance

#### MANUAL PUBLICATION DEFICIENCY REPORTING PROCEDURE

This regulation establishes procedures to be followed when a technical publication deficiency is noted and action to be taken to change the content of the publication.

- 1. Policy. These instructions pertain to all sections receiving distribution of the Maintenance and Flight Manual Group of publications.
- 2. Responsibilities. The Chief of Maintenance will be responsible for the implementation of these procedures.

#### 3. Procedures.

- a. ADP Form 1477-2, Manual Publication Deficiency Report, will be employed to accomplish the required changes. Each section will be provided with blank copies of this form. Additional copies may be obtained from the Inspection Section, Director of Materiel Office.
- b. The technician will fill out the form in draft handwritten or typed on the spot as deficiencies are discovered. The form will be screened by the section supervisor who will initial it prior to submittal. NOTE: Deficiencies discovered in the technical manuals which could result and/or are a safety of flight hazard will be immediately reported to his supervisor. The supervisor will immediately contact the Inspection Section and/or the Director of Materiel.
- c. The supervisor will then forward the draft completed ADP Form 1477-2 to the Inspection Section, Director of Materiel Office.
- d. The Inspection Section, will review the draft copy of the ADP Form 1477-2 for validity, readability, format, and assign a control number. The control number will be a numerical number, a dash and the last two digits of the year. (Example: 1-68, 2-68, 3-68, etc.).
- e. The reviewed draft copy of the ADP Form 1477-2 will be typed in final form in four (4) copies. Distribution will be two (2) copies to Project

Supersedes WRSP-IV Reg 66-1, 20 Mar 69. (For summary of revised, deleted, or added material, see signature page.)

OPR: D/MAT

DISTRIBUTION: X

### Approved For Release 2001/08/26: CIA-RDP33-02415A000600050030-6

#### FOR OFFICIAL USE ONLY

ATTG Reg 66-1

Headquarters, one copy to Inspection Section of the Director of Materiel, and one advance information copy to applicable contractor. Project Headquarters will evaluate and make further disposition.

R. A. SCHAMBER, Colonel, USAF Commander

1 Atch ADP Form 1477-2

Organizational designation changed.

## Approved For Release 2001/08/26 : CIA-RDP33-02415A000600050030-6

ATTG Reg 66-1

## - MANUAL PUBLICATION DEFICIENCY REPORT -

TO:	M	aintenance M	Manuals Group	)	Mode1	Publ No.		Date	
	$\mathbf{F}'$	light Manual	ls Group			Chg Date		ChgNo	
Date of This Report					Reply Do	esired	Yes	No	
SUBMITTED BY:					Signature				
TYPE OF ACTION RECOMMENDED:					C Requeste	d	Next	Change	
Affects Maintenance Procedures									
Page	No .	Fig. No.	Para or Index No.	F		Explanation suggestions			
						4			
		4-							
1477-2			N			2013			

Attachment 1